

BUILDING SAFETY CERTIFICATE

No.GBB 9822/2023

Dated: 07/06/2023

Certified that the existing building Dhruv Global School, Undri, Pune 411013 comprised of ground and 5(Five) upper floors occupied by Dhruv Global School, Undri, Pune 411013 have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **G.B. Bagade** on **05/06/2023** in the presence of **Mrs. Sharda Rao (Principal)** and that the building/premises is fit for occupancy up to classes **VII**, with effect from **07/06/2023 TO 06/06/2028** for a period of Five years in accordance with rule and subject to compliance of the specific conditions as appended.

1. It is a ground + five upper storied building constructed in and about one years back.
2. The said building is quite stable to withheld all types of load such as dead load, live load, wind load etc. & it does not create any harm to the entire building.

As per the Quality Assurance Certificate given by the licensed supervising engineer or the qualified builder / contractor. I further certify that to the best of my knowledge the structural work is carried out as per the prescribed applicable standards, codes, rules, regulations and stipulations, the material used, workmanship and methodology employed for the construction work are of the accepted standards, and the work is completed to render it fit for occupation for intended use.

This certificate is issued on the clear understanding that my overall design responsibility for the safety and proper performance of the structural design ceased, the moment any additions and / or alterations damages to the structural frame is caused by accident or by tampering with the geometrical sections of structural members for any purpose what so ever, or due to overloading of the structure, lack of maintenance or any act that is detrimental to the structure as a whole.

Issued on...**07/06/2023** at 11:00 am by **G.B.Bagade**.

Signature with Seal :

Name: G.B.Bagade.

Designation: Structural Designer.

Name & Address of Department/ Office: _____

(Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed/ issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.


G. B. BAGADE
B.E.(Civil) M.E.(Structure) M.I.E., F.I.V.
Structural Designer & Govt. Regd Valuer
L. No. P.M.C.222/201
P.M.C. Panel 6/242
M.I.E.-060835-6

G. B. Bagade

B.E. (Civil), M.E. (Structure) M.I.E. F.I.V.
Structural Designer & Govt Regd Valuer
Ex. Dy. City Engineer, Pune Municipal Corporation

Office : 478B/6A Anurag Society, Shivdarshan,
Parvati, Pune - 411 009. M. : 9423001236
Visiting Hours : 6 pm to 8 pm
Resi.: 83/1/11, Sarang Society, Sahakarnagar,
Parvati, Pune - 411 009. Tel.: 24225295

To,
The Principal,
Dhruv Global School,
Undri, Pune.

STRUCTURAL STABILITY REPORT

- 1) Name & Address of the Work : Stability Report of Dhruv Global School at Sr. No. 26/2, 26/2/1, 26/2/2, 26/2/2/2, 26/2/3/1, 26/2/3/2, 26/2/4/1, 26/2/4, Undri, Pune.
- 2) Name & Address of the Owner : M/S. Malpani Foundation.
Shri. Yashovardhan Sanjay Malpani.
Pune.
- 3) Name & Address of the Architect : Smt. Supriya Amar Joshi.
Pune.
- 4) Commencement Certificate No. & Date : CC/3966/21 Dated 17/03/2022
- 5) Completion Certificate No : Completion Certificate No - 7119
- 5) Year of Construction : 2022
- 6) Type of Structure : RCC Framed Structure
- 7) Number of Floors : Ground + Five upper Floors

I have inspected the site on 05/06/2023 and it is observed that

1. It is a Ground + five upper storied building constructed in and about one year back.
2. However completion certificate is issued for ground + one upper floor only and remaining completion of upper four floors is in progress.
3. The said building is quite stable to withheld all types of load such as dead load, live load, wind load etc. & it does not create any harm to the entire building.

Considering the above points I have no objection to issue structural stability report for the said building.

P.T.O

As per the Quality Assurance Certificate given by the licensed supervising engineer or the qualified builder / contractor, I further certify that to the best of my knowledge the structural work is carried out as per the prescribed applicable standards, codes, rules, regulations and stipulations, the material used, workmanship and methodology employed for the construction work are of the accepted standards, and the work is completed to render it fit for occupation for intended use.

This certificate is issued on the clear understanding that my overall design responsibility for the safety and proper performance of the structural design ceased, the moment any additions and / or alterations damages to the structural frame is caused by accident or by tampering with the geometrical sections of structural members for any purpose what so ever, or due to overloading of the structure, lack of maintenance or any act that is detrimental to the structure as a whole.

This certificate is valid up to – 07/06/2023 to 06/06/2028

Certificate No: GBB/9822/2023

Date : 07/06/2023

Place : Pune


G. B. BAGADE
BE (Civil) M.E. (Structure) M.I.E., F.I.V.
Structural Designer & Govt. Regd Valuer
L. No. P.M.C. 222/201
P.M.C. Panel 6/242
M.I.E.-060835-6